

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 095015	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/04/2010
---	--	---	--

NAME OF PROVIDER OR SUPPLIER

CAROLYN BOONE LEWIS HEALTH CARE CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE

**1380 SOUTHERN AVE SE
WASHINGTON, DC 20032**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS- REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	INITIAL COMMENTS Surveyor: 01300 On August 5, 2010 a Life Safety Code Survey was completed at your Facility. The following findings were observed during a tour of your facility on August 5, 2010.	K 000	Carolyn Boone Lewis Health Care Center, "CBL", is filing this Plan of Correction in accordance with the compliance requirements for NFPA 101 Life Safety Code Standards. This Plan of Correction constitutes the facility's written allegation of compliance for the deficiencies cited. However, submission of this Plan of Correction does not constitute admission of the facts or conclusions cited.	
K 017 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Corridors are separated from use areas by walls constructed with at least ½ hour fire resistance rating. In sprinklered buildings, partitions are only required to resist the passage of smoke. In non-sprinklered buildings, walls properly extend above the ceiling. (Corridor walls may terminate at the underside of ceilings where specifically permitted by Code. Charting and clerical stations, waiting areas, dining rooms, and activity spaces may be open to the corridor under certain conditions specified in the Code. Gift shops may be separated from corridors by non-fire rated walls if the gift shop is fully sprinklered.) 19.3.6.1, 19.3.6.2.1, 19.3.6.5 This STANDARD is not met as evidenced by: Surveyor: 01300 Based on observations during the Life Safety Code Inspection it was determined that penetrations were observed in wall surfaces above ceiling tiles in smoke barrier walls, on the first floor in one (1) one (1) observations, in wall surfaces above the Activity Room Ground Floor Level in two (2) of two (2) observations, in wall	K 017	K 017 NFPA 101 Life Safety Code Standard 1 a). <u>Corrective Actions</u> No resident(s) was (were) negatively impacted. The 12x12 inch opening above ceiling tiles in the residents first floor dining room was corrected immediately. b). <u>Identification of Deficient Practices & Corrective Actions</u> The Maintenance staff checked facility-wide above ceiling tile areas and have corrected upon discovery penetrations found. c). <u>Measures/Systematic Changes</u> <ul style="list-style-type: none">Maintenance staff were in-serviced by the Director of Maintenance regarding NFPA requirements in regard to the monitoring of penetrations/openings above ceiling tiles as part of the monthly Preventative Maintenance Program to ensure compliance.Above ceiling tile checks have been added to maintenance inspection form to be checked during monthly rounds. d). <u>Monitoring</u> The findings and corrections of the penetrations/openings above ceiling tiles will be reported to the monthly CQI committee until it has been determined by the committee that a quarterly report is effective. 2a). <u>Corrective Actions</u> No resident(s) was (were) negatively impacted. Two penetrations above wall surfaces in the activity ground floor level	08/04/10 10/26/10 08/20/10 10/28/10 08/04/10

TITLE

(X6) DATE

Denise Chadwick Wright LNA 10/26/10
Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 095015	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/04/2010
NAME OF PROVIDER OR SUPPLIER CAROLYN BOONE LEWIS HEALTH CARE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1380 SOUTHERN AVE SE WASHINGTON, DC 20032		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS- REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 017	Continued From page 1 surfaces above tiles near room 246 in one (1) of eight (8) observations, above the entrance door to room 243 in one (1) of eight (8) observations. The findings include: 1. A 12 x 12 inch opening was observed in wall surfaces above ceiling tiles in the residents Dining Room on the first floor in one (1) one (1) observations at 11:45 AM on August 7, 2010. 2. Two penetrations, approximately 1-2 inches were observed in wall surfaces above the Activity Room Ground Floor Level in two (2) of two (2) observations at 11:45 AM on August 7, 2010. 3. A 12 X 14 inch penetration was observed in wall surfaces above tiles near room 246 in one (1) of eight (8) observations at 11:55 AM on August 7, 2010. 4. A 2-3 inch penetration was observed above the entrance door to room 243 in one (1) of eight (8) observations at 12:10 PM on August 7, 2010. The findings were observed in the presence of employees # 1, 13, 14 and 31	K 017	Continued from page 1 were immediately corrected. b). Identification of Deficient Practices & Corrective Actions The Maintenance staff checked facility-wide above ceiling tile areas and have corrected Upon discovery penetrations found. c). Measures/Systematic Changes • Maintenance staff were in-serviced by the Director of Maintenance regarding NFPA requirements in regard to the monitoring of penetrations/openings above ceiling tiles as part of the monthly Preventative Maintenance Program to ensure compliance. • Above ceiling tile checks have been added to maintenance inspection form to be checked during monthly rounds. d). Monitoring The findings and corrections of the penetrations/openings above ceiling tiles will be reported to the monthly CQI committee until it has been determined by the committee that a quarterly report is effective. 3 a). Corrective Actions No resident(s) was (were) negatively impacted. The 12x14 inch opening above ceiling tiles near room 246 was corrected.	10/26/10 8/20/10	
K 018 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1¾ inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6	K 018	b). Identification of Deficient Practices & Corrective Actions The Maintenance staff checked facility-wide above ceiling tile areas and have corrected Upon discovery penetrations found. c). Measures/Systematic Changes • Maintenance staff were in-serviced by the Director of Maintenance regarding NFPA requirements in regard to the monitoring of penetrations/openings above ceiling tiles as part of the monthly Preventative Maintenance Program to ensure compliance.	10/28/10 08/09/10 10/26/10 08/20/10	

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

If continuation sheet Page 3 of 6

Continued From Page 3 of 6

b). Identification of Deficient Practices & Corrective Actions

The Maintenance staff checked facility-wide door closures and latching. Corrections have been made on discovery . 09/26/10

c). Measures/Systematic Changes 08/20/10

- Maintenance staff were in-serviced by the Director of Maintenance regarding NFPA requirements in regard to the monitoring of door latching/closure as part of the monthly Preventative Maintenance Program to ensure compliance.
- Door latch/closure checks have been added to maintenance inspection form to be checked during monthly rounds.

d). Monitoring

The findings and corrections of the Door latching/closures will be reported to the monthly CQI committee until it has been determined by the committee that a quarterly report is effective. 10/28/10

2 a). Corrective Actions

a). No resident(s) was (were) negatively impacted. The entrance door to the Shower Room has been corrected. 08/06/10

b). Identification of Deficient Practices & Corrective Actions

The Maintenance staff checked facility-wide door closures and latching. Corrections have been made on discovery . 09/26/10

c). Measures/Systematic Changes 08/20/10

- Maintenance staff were in-serviced by the Director of Maintenance regarding NFPA requirements in regard to the monitoring of door latching/closure as part of the monthly Preventative Maintenance Program to ensure compliance.
- Door latch/closure checks have been added to maintenance inspection form to be checked during monthly rounds.

d). Monitoring

The findings and corrections of the Door latching/closures will be reported to the monthly CQI committee until it has been determined by the committee that a quarterly report is effective. 10/28/10

Continued From Page3b of 6

3a). Corrective Actions

No resident(s) was (were) negatively impacted.
The entrance doors to rooms 212 and 246
have been adjusted to close properly.

10/12/10

b). Identification of Deficient Practices & Corrective Actions

The Maintenance staff checked facility-wide
door closures and latching. Corrections have
been made on discovery .

09/26/10

c). Measures/Systematic Changes

08/20/10

- Maintenance staff were in-serviced by the Director of Maintenance regarding NFPA requirements in regard to the monitoring of door latching/closure as part of the monthly Preventative Maintenance Program to ensure compliance.
- Door latch/closure checks have been added to maintenance inspection form to be checked during monthly rounds.

d). Monitoring

The findings and corrections of the
Door latching/closures will be reported
to the monthly CQI committee until it has been
determined by the committee that a quarterly
report is effective.

10/28/10

4 a). Corrective Actions

The closet doors to rooms 212, 304, 309,
322, 314 and 346 were replaced to
prevent impediment with the entrance
door.

10/13/10

b). Identification of Deficient Practices & Corrective Actions

Maintenance staff have performed a
facility wide inspection to ensure all
closet doors with the potential to impede
the entrance doors from full closure when
opened are replaced. Closet doors have
been ordered.

10/25/10

c). Measures/Systematic Changes

Maintenance staff were in-serviced by
the Director of Maintenance regarding
the NFPA requirement in regard to the
monitoring of door closing impediment
as part of the monthly Preventative
Maintenance Program to ensure compliance.

10/18/10

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 095015	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/04/2010
NAME OF PROVIDER OR SUPPLIER CAROLYN BOONE LEWIS HEALTH CARE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1380 SOUTHERN AVE SE WASHINGTON, DC 20032		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS- REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 018	Continued From page 3 2. The entrance door to the Shower Room on the First Floor failed to close without assistance when tested in one (1) of six (6) observations at 12:20 PM on August 5, 2010. 3. During the Life Safety Code tour of the facility it was determined that the entrance doors to rooms 212 and 246 was difficult to open and close by staff when the door was tested in one (1) of five (5) observations at 1:30 PM on August 5, 2010. 4. Closet doors located near the entrances doors to resident rooms, impeded the entrance doors from full closing when closet doors were in the open position in rooms 212, 304, 309, 322, 314 and 346 in six (6) of 13 observations between 11:00 AM and 2:45 PM on August 5, 2010. These observations were made in the presence of employees #1, 13, 14, and 31.	K 018			
K 045 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Illumination of means of egress, including exit discharge, is arranged so that failure of any single lighting fixture (bulb) will not leave the area in darkness. (This does not refer to emergency lighting in accordance with section 7.8.) 19.2.8 This STANDARD is not met as evidenced by: Surveyor: 01300 Based on observations during the survey period it was determined that wall lamps in stairwells failed to provide illumination in the event of a fire as means to provide access to exits to assist residents and staff in the event of a fire in two (2)	K 045			

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 4WTJ21 Facility ID: HCI If continuation sheet Page 5 of 6

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 4WTJ21 Facility ID: HCI If continuation sheet Page 6 of 6

Continued From Page 6

c). Measures/Systematic Changes

Maintenance staff were in-serviced by the Director of Maintenance regarding the NFPA requirement in regard to base board surfaces and the monitoring of baseboard surfaces as part of the monthly Preventative Maintenance Program to ensure compliance.

10/18/10

d). Monitoring

The findings and corrections of the base board findings will be reported to the monthly CQI committee on a monthly basis until it has been determined by the committee that this area of concern can be reported quarterly.

10/28/10

2a). Corrective Actions

The mattress in room 137 was disposed of and replaced.

8/4/10

b). Identification of Deficient Practices&

A facility-wide inventory and audit of all beds and mattresses have been conducted to identify mattresses in need of replacement. Mattress replacement has been initiated and a schedule for replacement has been initiated.

08/25/10

c). Measures/Systematic Changes

Environmental Services Staff will be in-serviced on the NFPA requirement and the monitoring of mattresses as part of the weekly Cleaning Program to ensure compliance.

10/19/10

d). Monitoring

The findings and corrections of the mattress findings will be reported to the monthly CQI committee on a monthly basis until it has been determined by the committee that this area of concern can be reported quarterly.

10/28/10